

184	GX-B1423/20-Y-22876	2022年4月4日	合格		
185	GX-B1423/20-Y-22877	2022年4月4日	合格		
186	GX-B1423/20-Y-22878	2022年4月4日	合格		

187	GX-B1423/20-Y-22879	2022年4月4日	合格	
188	GX-B1423/20-Y-22880	2022年4月4日	合格	
189	GX-B1423/20-Y-22881	2022年4月4日	合格	

190	GX-B1423/20-Y-22882	2022年4月4日	合格		
191	GX-B1423/20-Y-22883	2022年4月4日	合格		
192	GX-B1423/20-Y-22884	2022年4月4日	合格		

193	GX-B1423/20-Y-22885	2022年4月4日	合格		
194	GX-B1423/20-Y-22886	2022年4月4日	合格		
195	GX-B1423/20-Y-22887	2022年4月4日	合格		

196	GX-B1423/20-Y-22888	2022年4月4日	合格	
197	GX-B1423/20-Y-22889	2022年4月4日	合格	
198	GX-B1423/20-Y-22890	2022年4月4日	合格	

199	GX-B1423/20-Y-22891	2022年4月4日	合格	 A yellow dump truck with license plate H-2073 is parked on a dirt road. Two workers, one in a grey jacket and yellow helmet, and another in a camouflage jacket and black helmet, stand in front of the truck. The date 2022/2/15 is visible in the bottom right corner.
200	GX-B1423/20-Y-22892	2022年4月4日	合格	 A yellow dump truck with license plate H-2093 is parked on a dirt road. Two workers, one in a red jacket and red helmet, and another in a camouflage jacket and black helmet, stand in front of the truck. The date 2022/2/15 is visible in the bottom right corner.
201	GX-B1423/20-Y-22893	2022年4月4日	合格	 A yellow dump truck with license plate H-2093 is parked on a dirt road. Two workers, one in a blue and yellow safety vest and yellow helmet, and another in a camouflage jacket and black helmet, stand in front of the truck. The date 2022/2/15 is visible in the bottom right corner.

202	GX-B1423/20-Y-22894	2022年4月4日	合格	 A yellow dump truck with the number 460 on its side. Two workers wearing safety vests and hard hats are standing in front of the truck. The date 2022/2/15 is visible in the bottom right corner of the photo.
203	GX-B1423/20-Y-22895	2022年4月4日	合格	 A yellow dump truck with MT86M on its side. Two workers wearing safety vests and hard hats are standing in front of the truck. The date 2022/2/15 is visible in the bottom right corner of the photo.
204	GX-B1423/20-Y-22896	2022年4月4日	合格	 A yellow dump truck with MT86M on its side. Two workers wearing safety vests and hard hats are standing in front of the truck. The date 2022/2/15 is visible in the bottom right corner of the photo.

205	GX-B1423/20-Y-22897	2022年4月4日	合格		
206	GX-B1423/20-Y-22898	2022年4月4日	合格		
207	GX-B1423/20-Y-22899	2022年4月5日	合格		

208	GX-B1423/20-Y-22900	2022年4月5日	合格	 A yellow MT858 dump truck is parked on a dirt surface. Two people are standing in front of the truck. The person on the left is wearing a red jacket and black pants. The person on the right is wearing a camouflage jacket and black pants. The truck has 'MT858' and 'B-3117' written on its side. A yellow timestamp '2022/2/16' is visible in the bottom right corner of the photo.
209	GX-B1423/20-Y-22901	2022年4月5日	合格	 A yellow MT858 dump truck is parked on a dirt surface. Two people are standing in front of the truck. The person on the left is wearing a red jumpsuit and a yellow hard hat. The person on the right is wearing a camouflage jacket and black pants. The truck has 'MT858' and 'B-3117' written on its side. A yellow timestamp '2022/2/16' is visible in the bottom right corner of the photo.
210	GX-B1423/20-Y-22902	2022年4月5日	合格	 A yellow MT858 dump truck is parked on a dirt surface. Two people are standing in front of the truck. The person on the left is wearing a yellow safety vest over a black jacket and a yellow hard hat. The person on the right is wearing a camouflage jacket and black pants. The truck has 'MT858' and 'B-3117' written on its side. A yellow timestamp '2022/2/16' is visible in the bottom right corner of the photo.

211	GX-B1423/20-Y-22903	2022年4月5日	合格	
212	GX-B1423/20-Y-22904	2022年4月5日	合格	
213	GX-B1423/20-Y-22905	2022年4月5日	合格	

214	GX-B1423/20-Y-22906	2022年4月5日	合格	
215	GX-B1423/20-Y-22907	2022年4月5日	合格	

216	GX-B1423/20-Y-22908	2022年4月5日	合格	
217	GX-B1423/20-Y-22909	2022年4月5日	合格	

218	GX-B1423/20-Y-22910	2022年4月5日	合格	
219	GX-B1423/20-Y-22911	2022年4月5日	合格	

220	GX-B1423/20-Y-22912	2022年4月5日	合格	
221	GX-B1423/20-Y-22913	2022年4月5日	合格	

222	GX-B1423/20-Y-22914	2022年4月5日	合格	
223	GX-B1423/20-Y-22915	2022年4月5日	合格	

224	GX-B1423/20-Y-22916	2022年4月5日	合格	
225	GX-B1423/20-Y-22917	2022年4月5日	合格	

226	GX-B1423/20-Y-22918	2022年4月5日	合格	
227	GX-B1423/20-Y-22919	2022年4月5日	合格	

228	GX-B1423/20-Y-22920	2022年4月5日	合格	 A yellow MT860 dump truck is shown from the front. Two people are standing in front of the truck: one in a brown jacket and black pants, and another in a blue jacket, red pants, and a yellow hard hat. The truck has 'MT860' and '120' visible on its front. A yellow timestamp '2022/2/17' is in the bottom right corner.
229	GX-B1423/20-Y-22921	2022年4月5日	合格	 A yellow MT86H dump truck is shown from the side. Two people are standing in front of the truck: one in a brown jacket and black pants, and another in a blue jacket, red pants, and a yellow hard hat. The truck has 'MT86H' and '120' visible on its side. A yellow timestamp '2022/2/17' is in the bottom right corner.

230	GX-B1423/20-Y-22922	2022年4月5日	合格	
231	GX-B1423/20-Y-22923	2022年4月5日	合格	

232	GX-B1423/20-Y-22924	2022年4月5日	合格	 A yellow dump truck, model MT86H, is parked on a dirt surface. Two people, one wearing a yellow hard hat and the other a black hard hat, are standing in front of the truck. The date 2022/2/18 is visible in the bottom right corner of the photo.
233	GX-B1423/20-Y-22925	2022年4月5日	合格	 A yellow dump truck, model MT86H, is parked on a dirt surface. Two people, one wearing a yellow hard hat and the other a blue and yellow safety vest, are standing in front of the truck. The date 2022/2/18 is visible in the bottom right corner of the photo.

234	GX-B1423/20-Y-22926	2022年4月5日	合格	
235	GX-B1423/20-Y-22927	2022年4月5日	合格	

236	GX-B1423/20-Y-22928	2022年4月5日	合格	
237	GX-B1423/20-Y-22929	2022年4月5日	合格	

238	GX-B1423/20-Y-22930	2022年4月5日	合格	
239	GX-B1423/20-Y-22931	2022年4月5日	合格	

240	GX-B1423/20-Y-22932	2022年4月5日	合格	
241	GX-B1423/20-Y-22933	2022年4月5日	合格	

242	GX-B1423/20-Y-22934	2022年4月5日	合格	 A yellow MTB5 dump truck is parked on a dirt surface. Two workers are standing in front of it: one in a blue jacket and yellow safety vest, and another in a brown jacket. A yellow timestamp '2022/2/19' is in the bottom right corner.
243	GX-B1423/20-Y-22935	2022年4月5日	合格	 A yellow MTB5 dump truck is parked on a dirt surface. Two workers are standing in front of it: one in a brown jacket and the other in a blue jacket and yellow safety vest. A yellow timestamp '2022/2/19' is in the bottom right corner.

244	GX-B1423/20-Y-22936	2022年4月5日	合格	
245	GX-B1423/20-Y-22937	2022年4月5日	合格	

246	GX-B1423/20-Y-22938	2022年4月5日	合格	
247	GX-B1423/20-Y-22939	2022年4月5日	合格	

248	GX-B1423/20-Y-22940	2022年4月5日	合格	
249	GX-B1423/20-Y-22941	2022年4月5日	合格	

250	GX-B1423/20-Y-22942	2022年4月5日	合格	
251	GX-B1423/20-Y-22943	2022年4月5日	合格	

252	GX-B1423/20-Y-22944	2022年4月5日	合格	
253	GX-B1423/20-Y-22945	2022年4月5日	合格	

254	GX-B1423/20-Y-22946	2022年4月5日	合格	
255	GX-B1423/20-Y-22947	2022年4月5日	合格	

256	GX-B1423/20-Y-22948	2022年4月5日	合格	
257	GX-B1423/20-Y-22949	2022年4月5日	合格	

258	GX-B1423/20-Y-22950	2022年4月5日	合格	 A yellow MT86H dump truck is parked on a dirt surface under a clear blue sky. Two workers are standing in front of the truck: one wearing a yellow safety vest and red pants, and the other in a brown jacket and dark pants. A yellow timestamp '2022/2/20' is visible in the bottom right corner of the photo.
259	GX-B1423/20-Y-22951	2022年4月5日	合格	 A yellow MT86H dump truck is parked on a dirt surface under a clear blue sky. Two workers are standing in front of the truck: one wearing a yellow safety vest and red pants, and the other in a brown jacket and dark pants. A yellow timestamp '2022/2/20' is visible in the bottom right corner of the photo.

260	GX-B1423/20-Y-22952	2022年4月5日	合格	
261	GX-B1423/20-Y-22953	2022年4月5日	合格	

262	GX-B1423/20-Y-22954	2022年4月5日	合格	
263	GX-B1423/20-Y-22955	2022年4月5日	合格	

264	GX-B1423/20-Y-221042	2022年4月5日	合格	
265	GX-B1423/20-Y-221043	2022年4月5日	合格	

266	GX-B1423/20-Y-221044	2022年4月5日	合格	
267	GX-B1423/20-Y-221045	2022年4月5日	合格	
268	GX-B1423/20-Y-221046	2022年4月5日	合格	

269	GX-B1423/20-Y-221047	2022年4月5日	合格	
270	GX-B1423/20-Y-221048	2022年4月5日	合格	
271	GX-B1423/20-Y-221049	2022年4月5日	合格	

272	GX-B1423/20-Y-221050	2022年4月5日	合格	 A yellow dump truck with the identification number S-121 is parked on a dirt surface. Two workers in winter clothing and safety vests stand in front of the truck. The truck's bed is raised. A yellow timestamp '2022/2/21' is visible in the bottom right corner of the photo.
273	GX-B1423/20-Y-221051	2022年4月5日	合格	 A yellow dump truck with the identification number S-118 is parked on a dirt surface. Two workers in winter clothing and safety vests stand in front of the truck. The truck's bed is raised. A yellow timestamp '2022/2/21' is visible in the bottom right corner of the photo.
274	GX-B1423/20-Y-221052	2022年4月5日	合格	 A yellow dump truck with the identification number S-120 is parked on a dirt surface. Two workers in winter clothing and safety vests stand in front of the truck. The truck's bed is raised. A yellow timestamp '2022/2/22' is visible in the bottom right corner of the photo.

275	GX-B1423/20-Y-221053	2022年4月5日	合格	
276	GX-B1423/20-Y-221054	2022年4月5日	合格	
277	GX-B1423/20-Y-221055	2022年4月5日	合格	

278	GX-B1423/20-Y-221056	2022年4月5日	合格		
279	GX-B1423/20-Y-221057	2022年4月5日	合格		
280	GX-B1423/20-Y-221058	2022年4月5日	合格		

281	GX-B1423/20-Y-221059	2022年4月5日	合格		
282	GX-B1423/20-Y-221060	2022年4月5日	合格		
283	GX-B1423/20-Y-221061	2022年4月5日	合格		

284	GX-B1423/20-Y-221062	2022年4月5日	合格	
285	GX-B1423/20-Y-221063	2022年4月5日	合格	
286	GX-B1423/20-Y-221064	2022年4月5日	合格	

287	GX-B1423/20-Y-221065	2022年4月5日	合格	
288	GX-B1423/20-Y-221066	2022年4月5日	合格	
289	GX-B1423/20-Y-221067	2022年4月5日	合格	

290	GX-B1423/20-Y-221068	2022年4月5日	合格	
291	GX-B1423/20-Y-221069	2022年4月5日	合格	
292	GX-B1423/20-Y-221070	2022年4月5日	合格	

293	GX-B1423/20-Y-221071	2022年4月5日	合格		
294	GX-B1423/20-Y-221072	2022年4月5日	合格		
295	GX-B1423/20-Y-221073	2022年4月5日	合格		

296	GX-B1423/20-Y-221074	2022年4月5日	合格		
297	GX-B1423/20-Y-221075	2022年4月5日	合格		
298	GX-B1423/20-Y-221076	2022年4月5日	合格		

299	GX-B1423/20-Y-221077	2022年4月5日	合格	
300	GX-B1423/20-Y-221078	2022年4月5日	合格	
301	GX-B1423/20-Y-221079	2022年4月5日	合格	

302	GX-B1423/20-Y-221080	2022年4月5日	合格	 A yellow Weichai dump truck with the license plate S-123 is parked in front of a white building. Two workers wearing hard hats and safety vests are standing in front of the truck. A yellow date stamp '2022/2/23' is visible in the bottom right corner of the photo.
303	GX-B1423/20-Y-221081	2022年4月5日	合格	 A yellow Weichai dump truck with the license plate S-123 is parked in front of a white building. Two workers wearing hard hats and safety vests are standing in front of the truck. The bottom portion of the image is obscured by a grey rectangular block.
304	GX-B1423/20-Y-221082	2022年4月5日	合格	 A yellow Weichai dump truck with the license plate S-127 is parked in front of a white building. Two workers wearing hard hats and safety vests are standing in front of the truck. A yellow date stamp '2022/2/23' is visible in the bottom right corner of the photo.

305	GX-B1423/20-Y-221083	2022年4月5日	合格		
306	GX-B1423/20-Y-221084	2022年4月5日	合格		
307	GX-B1423/20-Y-221085	2022年4月5日	合格		

308	GX-B1423/20-Y-221086	2022年4月5日	合格	 A yellow TONLY dump truck with the number 28 on its side. Two workers in winter clothing and hard hats stand in front of the truck. A yellow timestamp '2022/2/23' is in the bottom right corner.	
309	GX-B1423/20-Y-221087	2022年4月5日	合格	 A yellow TONLY dump truck with the number 22 on its side. Two workers in winter clothing and hard hats stand in front of the truck. A yellow timestamp '2022/2/23' is in the bottom right corner.	
310	GX-B1423/20-Y-221088	2022年4月5日	合格	 A yellow TONLY dump truck with the number 23 on its side. Two workers in winter clothing and hard hats stand in front of the truck. A yellow timestamp '2022/2/23' is in the bottom right corner.	

311	GX-B1423/20-Y-221089	2022年4月5日	合格		
312	GX-B1423/20-Y-221090	2022年4月5日	合格		
313	GX-B1423/20-Y-221091	2022年4月5日	合格		

314	GX-B1423/20-Y-221092	2022年4月5日	合格	 A yellow dump truck with the license plate S-324 is parked in front of a white building. Two workers, one in a yellow safety vest and the other in a camouflage jacket, are standing in front of the truck. The date 2022/2/24 is visible in the bottom right corner of the photo.
315	GX-B1423/20-Y-221093	2022年4月5日	合格	 A yellow dump truck with the license plate S-322 is parked in front of a white building. Two workers, one in a yellow safety vest and the other in a camouflage jacket, are standing in front of the truck. The date 2022/2/24 is visible in the bottom right corner of the photo.
316	GX-B1423/20-Y-221094	2022年4月5日	合格	 A yellow dump truck with the license plate S-305 is parked in front of a white building. Two workers, one in a yellow safety vest and the other in a camouflage jacket, are standing in front of the truck. The date 2022/2/24 is visible in the bottom right corner of the photo.

317	GX-B1423/20-Y-221095	2022年4月5日	合格	 A yellow dump truck is parked on a dirt lot. Two workers in camouflage uniforms and hard hats stand in front of it. The truck has 'S-302' on its side. A yellow timestamp '2022/2/24' is in the bottom right corner.
318	GX-B1423/20-Y-221096	2022年4月5日	合格	 A yellow dump truck is parked on a dirt lot. Two workers in camouflage uniforms and hard hats stand in front of it. The truck has 'S-325' on its side. A yellow timestamp '2022/2/24' is in the bottom right corner.
319	GX-B1423/20-Y-221097	2022年4月5日	合格	 A yellow dump truck is parked on a dirt lot. Two workers in camouflage uniforms and hard hats stand in front of it. The truck has 'S-375' on its side. A yellow timestamp '2022/2/24' is in the bottom right corner.

320	GX-B1423/20-Y-221098	2022年4月5日	合格	
321	GX-B1423/20-Y-221099	2022年4月5日	合格	
322	GX-B1328/20-Y-22020	2022/4/7	合格	
323	GX-B1328/20-Y-22021	2022/4/7	合格	
324	GX-B1328/20-Y-22022	2022/4/7	合格	
325	GX-B1328/20-Y-22023	2022/4/7	合格	
326	GX-B1328/20-Y-22024	2022/4/7	合格	

327	GX-B1495/20-Y-22170 ~22186	2022/4/7	合格	
328	GX-B1495/20-Y-22187 ~22196	2022/4/7	合格	
329	GX-B1495/20-Y-22197	2022/4/7	合格	
330	GX-B1495/20-Y-22198 ~22199	2022/4/7	合格	
331	GX-B1495/20-Y-22201 ~22209	2022/4/7	合格	
332	GX-B1495/20-Y-22210 ~22224	2022/4/7	合格	
333	GX-B1312/20-Y-22089	2022/4/7	合格	
334	GX-B495/20-Y-22231~ 22235	2022/4/7	合格	
335	GX-B1547/20-Y-22011 ~22019	2022/4/7	合格	
336	GX-B1329/21-Y-22003 ~22004	2022/4/7	合格	
337	GX-B1321/20-Y-22055 ~22066	2022/4/7	合格	
338	GX-B1321/20-Y-22067 ~22076	2022/4/7	合格	
339	GX-B1321/20-Y-22077 ~22083	2022/4/7	合格	
340	GX-B1321/20-Y-22084 ~22091	2022/4/7	合格	
341	GX-B1350/21-Y-22014	2022/4/7	合格	
342	GX-B1350/21-Y-22015	2022/4/7	合格	

343	GX-B1350/21-Y-22016	2022/4/7	合格	
344	GX-B1350/21-Y-22017	2022/4/7	合格	
345	GX-B1350/21-Y-22018	2022/4/7	合格	
346	GX-B1350/21-Y-22019	2022/4/7	合格	
347	GX-B1350/21-Y-22020	2022/4/7	合格	
348	GX-B1350/21-Y-22021	2022/4/7	合格	
349	GX-B1312/20-Y-22064 ～22065	2022/4/7	合格	
350	GX-B1312/20-Y-22066 ～22067	2022/4/7	合格	
351	GX-B1312/20-Y-22068	2022/4/7	合格	
352	GX-B1312/20-Y-22069 ～22070	2022/4/7	合格	
353	GX-B1312/20-Y-22071	2022/4/7	合格	
354	GX-B1312/20-Y-22072 ～22073	2022/4/7	合格	
355	GX-B1312/20-Y-22074	2022/4/7	合格	
356	GX-B1312/20-Y-22075	2022/4/7	合格	
357	GX-B1312/20-Y-22076	2022/4/7	合格	
358	GX-B1312/20-Y-22077	2022/4/7	合格	

359	GX-B1312/20-Y-22078 ~22080	2022/4/7	合格	
360	GX-B1312/20-Y-22081	2022/4/7	合格	
361	GX-B1312/20-Y-22082	2022/4/7	合格	
362	GX-B1312/20-Y-22083 ~22084	2022/4/7	合格	
363	GX-B1312/20-Y-22085 ~22086	2022/4/7	合格	
364	GX-B1312/20-Y-22087 ~22088	2022/4/7	合格	