

序号	报告编号	发布日期	结论	影像资料
225	GX-B1308/21-Y-22011	2022年7月7日	合格	
226	GX-B1499/21-Y-22096	2022年7月7日	合格	

227	GX-B1499/21-Y-22097	2022年7月7日	合格	
228	GX-B1499/21-Y-22098	2022年7月7日	合格	

229	GX-B1561/20-Y-22002	2022年7月8日	合格	
-----	---------------------	-----------	----	---

230	GX-B1310/21-Y-22075	2022年7月7日	合格	
-----	---------------------	-----------	----	---

231	GX-B1310/21-Y-22076	2022年7月7日	合格	
-----	---------------------	-----------	----	---

232	GX-B1428/21-Y-22075	2022年7月7日	合格	
233	GX-B1428/21-Y-22076	2022年7月7日	合格	

234	GX-B1521/20-Y-22206	2022年7月9日	合格	
235	GX-B1521/20-Y-22207	2022年7月9日	合格	

236	GX-B1521/20-Y-22208	2022年7月9日	合格	
237	GX-B1521/20-Y-22209	2022年7月9日	合格	

238	GX-B1521/20-Y-22210	2022年7月9日	合格	
239	GX-B1521/20-Y-22211	2022年7月9日	合格	

240	GX-B1521/20-Y-22212	2022年7月9日	合格	
241	GX-B1521/20-Y-22213	2022年7月9日	合格	

242	GX-B1521/20-Y-22214	2022年7月9日	合格	
243	GX-B1521/20-Y-22215	2022年7月9日	合格	

244	GX-B1521/20-Y-22216	2022年7月9日	合格	
245	GX-B1521/20-Y-22217	2022年7月9日	合格	

246	GX-B1521/20-Y-22218	2022年7月9日	合格	
247	GX-B1521/20-Y-22219	2022年7月9日	合格	

248	GX-B1521/20-Y-22220	2022年7月9日	合格	
249	GX-B1539/20-Y-22123	2022年7月7日	合格	

250	GX-B1539/20-Y-22124	2022年7月7日	合格	
251	GX-B1539/20-Y-22125	2022年7月7日	合格	

252	GX-B1539/20-Y-22126	2022年7月7日	合格	
253	GX-B1521/20-Y-22199	2022年7月8日	合格	

254	GX-B1521/20-Y-22200	2022年7月8日	合格	 A yellow CAT excavator is shown working on a rocky, uneven terrain. The excavator's arm is extended, and it appears to be digging or moving material. The background shows a clear blue sky and some distant hills. A yellow timestamp "2022/6/25" is visible in the bottom right corner of the image.
255	GX-B1521/20-Y-22201	2022年7月8日	合格	 A yellow CAT excavator is shown on a flat, dirt-covered field. The excavator's arm is lowered, and it appears to be in a stationary position. A person is standing near the base of the excavator, providing a sense of scale. The background shows a clear blue sky with some clouds. A yellow timestamp "2022/6/25" is visible in the bottom right corner of the image.

256	GX-B1521/20-Y-22202	2022年7月8日	合格	
257	GX-B1521/20-Y-22203	2022年7月8日	合格	

258	GX-B1521/20-Y-22204	2022年7月8日	合格	 2022/6/29
259	GX-B1521/20-Y-22205	2022年7月8日	合格	 2022/6/29

260	GX-B1423/20-Y-222535	2022年7月7日	合格	
261	GX-B1423/20-Y-222536	2022年7月7日	合格	

262	GX-B1423/20-Y-222537	2022年7月7日	合格	
263	GX-B1423/20-Y-222538	2022年7月7日	合格	

264	GX-B1423/20-Y-222539	2022年7月7日	合格	
265	GX-B1423/20-Y-222540	2022年7月7日	合格	


266	GX-B1423/20-Y-222541	2022年7月7日	合格	
267	GX-B1423/20-Y-222542	2022年7月7日	合格	

268	GX-B1423/20-Y-222543	2022年7月7日	合格	
269	GX-B1423/20-Y-222544	2022年7月7日	合格	

270	GX-B1423/20-Y-222545	2022年7月7日	合格	
271	GX-B1423/20-Y-222546	2022年7月7日	合格	

272	GX-B1423/20-Y-222547	2022年7月7日	合格	
273	GX-B1423/20-Y-222548	2022年7月7日	合格	

274	GX-B1521/20-Y-22222	2022年7月7日	合格	
-----	---------------------	-----------	----	---

275	GX-B1521/20-Y-22223	2022年7月7日	合格	 A worker wearing a red hard hat and a light blue short-sleeved shirt is seated on a piece of heavy machinery, possibly a loader or excavator. He is looking down at something in his hands. The background shows a construction site with some equipment and a yellow date stamp '2022/6/27' in the bottom right corner.
276	GX-B1557/21-Y-22006	2022年7月8日	合格	 A yellow BANYE wheel loader is parked on a dirt construction site. Two workers in hard hats and work clothes are standing next to the machine. The background shows other construction equipment and a clear blue sky. A yellow date stamp '2022/6/27' is visible in the bottom right corner.

277	GX-B1310/21-Y-22077	2022年7月8日	合格	
-----	---------------------	-----------	----	---

278	GX-B1310/21-Y-22078	2022年7月8日	合格	
-----	---------------------	-----------	----	---

279	GX-B1428/21-Y-22077	2022年7月8日	合格	
-----	---------------------	-----------	----	---

280	GX-B1428/21-Y-22078	2022年7月8日	合格	
-----	---------------------	-----------	----	---

281	GX-B1428/21-Y-22079	2022年7月8日	合格	
-----	---------------------	-----------	----	---

282	GX-B1428/21-Y-22080	2022年7月8日	合格	
283	GX-B1559/21-Y-22013	2022年7月9日	合格	

284	GX-B1559/21-Y-22014	2022年7月9日	合格	 A worker wearing a light-colored long-sleeved shirt, dark pants, and a patterned bucket hat is operating a yellow forklift. The forklift is positioned in front of a white container. A yellow timestamp '2022/6/15' is visible in the bottom right corner of the photo.
285	GX-B1559/21-Y-22015	2022年7月9日	合格	 A worker wearing a light-colored long-sleeved shirt, dark pants, and a patterned bucket hat is standing next to a yellow forklift, holding a long tool or rod. The forklift is parked on a paved surface in front of a white container. A yellow timestamp '2022/6/15' is visible in the bottom right corner of the photo.

286	GX-B1559/21-Y-22016	2022年7月9日	合格	
287	GX-B1450/21-Y-22060	2022年7月9日	合格	

288	GX-B1450/21-Y-22061	2022年7月9日	合格	 A white heavy-duty vehicle, possibly a specialized truck or loader, with large black tires and a yellow hydraulic arm. Two workers wearing hard hats (one yellow, one red) and safety gear are standing next to the vehicle. The background shows an industrial or construction site with a building and a clear sky. A yellow timestamp '2022/7/9' is visible in the bottom right corner of the image.
289	GX-B1450/21-Y-22062	2022年7月9日	合格	 A white K5 truck with a yellow body, featuring the 'K5' logo on the front. Two workers wearing hard hats (one red, one yellow) and safety gear are standing next to the truck. The background shows an industrial or construction site with a building and a clear sky. A yellow timestamp '2022/7/9' is visible in the bottom right corner of the image.

290	GX-B1450/21-Y-22063	2022年7月9日	合格	
291	GX-B1450/21-Y-22064	2022年7月9日	合格	

292	GX-B1450/21-Y-22065	2022年7月9日	合格	 A photograph showing two workers in safety gear (hard hats, masks, and work clothes) standing next to a white pickup truck. The truck has "KS 10" written on the driver's side door. The background is a large industrial building. A yellow timestamp "2022/6/10" is visible in the bottom right corner of the photo.
293	GX-B1450/21-Y-22066	2022年7月9日	合格	 A photograph showing two workers in safety gear (hard hats, masks, and work clothes) standing in front of a white pickup truck. The truck has "KS 11" written on the driver's side door. The background is a large industrial building. A yellow timestamp "2022/6/11" is visible in the bottom right corner of the photo.

294	GX-B1450/21-Y-22067	2022年7月9日	合格	
295	GX-B1450/21-Y-22068	2022年7月9日	合格	

296	GX-B1450/21-Y-22069	2022年7月9日	合格	
297	GX-B1450/21-Y-22070	2022年7月9日	合格	

298	GX-B1450/21-Y-22071	2022年7月9日	合格	
299	GX-B1450/21-Y-22072	2022年7月9日	合格	

300	GX-B1450/21-Y-22073	2022年7月9日	合格	
301	GX-B1450/21-Y-22074	2022年7月9日	合格	

302	GX-B1450/21-Y-22075	2022年7月9日	合格	
303	GX-B1450/21-Y-22076	2022年7月9日	合格	

304	GX-B1450/21-Y-22077	2022年7月9日	合格	
305	GX-B1450/21-Y-22078	2022年7月9日	合格	

306	GX-B1450/21-Y-22079	2022年7月9日	合格	 2022/8/18
307	GX-B1450/21-Y-22080	2022年7月9日	合格	 2022/8/18

308	GX-B1450/21-Y-22081	2022年7月9日	合格	 A white truck with a crane, marked with '20' and '核定10T', parked in a lot. The date '2022/6/16' is visible in the bottom right corner of the image.
309	GX-B1450/21-Y-22082	2022年7月9日	合格	 A white truck with a crane, marked with '30' and '核定10T', parked in a lot. A worker is visible on top of the truck. The date '2022/6/16' is visible in the bottom right corner of the image.

310	GX-B1423/20-Y-222648	2022. 7. 9	合格	
311	GX-B1423/20-Y-222649	2022. 7. 9	合格	

312	GX-B1423/20-Y-222650	2022. 7. 9	合格	 A yellow TONLY M-160 dump truck is parked on a dirt surface. Two workers wearing hard hats and safety gear stand in front of the truck. The date stamp '2022/6/18' is visible in the bottom right corner of the photo.
313	GX-B1423/20-Y-222651	2022. 7. 9	合格	 A yellow TONLY M-160 dump truck is parked on a dirt surface. Two workers wearing hard hats and safety gear stand in front of the truck. The date stamp '2022/6/18' is visible in the bottom right corner of the photo.

314	GX-B1423/20-Y-222652	2022. 7. 9	合格	
315	GX-B1423/20-Y-222653	2022. 7. 9	合格	

316	GX-B1423/20-Y-222654	2022. 7. 9	合格	
317	GX-B1423/20-Y-222655	2022. 7. 9	合格	

318	GX-B1423/20-Y-222656	2022. 7. 9	合格	
319	GX-B1423/20-Y-222657	2022. 7. 9	合格	

320	GX-B1423/20-Y-222658	2022. 7. 9	合格	
321	GX-B1423/20-Y-222659	2022. 7. 9	合格	

322	GX-B1423/20-Y-222660	2022. 7. 9	合格	
323	GX-B1423/20-Y-222661	2022. 7. 9	合格	

324	GX-B1423/20-Y-222662	2022. 7. 9	合格	
325	GX-B1423/20-Y-222663	2022. 7. 9	合格	

326	GX-B1423/20-Y-222664	2022. 7. 9	合格	
327	GX-B1423/20-Y-222665	2022. 7. 9	合格	

328	GX-B1423/20-Y-222666	2022. 7. 9	合格	
329	GX-B1423/20-Y-222667	2022. 7. 9	合格	

330	GX-B1423/20-Y-222668	2022. 7. 9	合格	
331	GX-B1423/20-Y-222669	2022. 7. 9	合格	

332	GX-B1423/20-Y-222670	2022. 7. 9	合格	
333	GX-B1423/20-Y-222671	2022. 7. 9	合格	

334	GX-B1423/20-Y-222672	2022. 7. 9	合格	
335	GX-B1423/20-Y-222673	2022. 7. 9	合格	

336	GX-B1423/20-Y-222674	2022. 7. 9	合格	
337	GX-B1423/20-Y-222675	2022. 7. 9	合格	

338	GX-B1423/20-Y-222676	2022. 7. 9	合格	
339	GX-B1423/20-Y-222677	2022. 7. 9	合格	

340	GX-B1423/20-Y-222678	2022. 7. 9	合格	
341	GX-B1423/20-Y-222679	2022. 7. 9	合格	

342	GX-B1423/20-Y-222680	2022. 7. 9	合格	
-----	----------------------	------------	----	---

343	GX-B1423/20-Y-222681	2022. 7. 9	合格	
344	GX-B1423/20-Y-222682	2022. 7. 9	合格	

345	GX-B1423/20-Y-222683	2022. 7. 9	合格	
346	GX-B1423/20-Y-222684	2022. 7. 9	合格	

347	GX-B1423/20-Y-222685	2022. 7. 9	合格	 A photograph showing two workers standing next to a large yellow dump truck. The worker on the left is wearing a red hard hat, a white face mask, and a grey work uniform. The worker on the right is wearing a yellow hard hat, a yellow high-visibility vest over a grey shirt, and dark pants. The truck is yellow with the number '22' visible on its side. A yellow timestamp '2022/6/28' is in the bottom right corner of the photo.
348	GX-B1423/20-Y-222686	2022. 7. 9	合格	 A photograph showing two workers standing in front of the cab of a yellow truck. The worker on the left is wearing a red hard hat, a white face mask, and a grey work uniform. The worker on the right is wearing a yellow hard hat, a yellow high-visibility vest over a black shirt, and dark pants. The truck's front grille and headlights are visible. A yellow timestamp '2022/6/28' is in the bottom right corner of the photo.

349	GX-B1423/20-Y-222687	2022. 7. 9	合格	
350	GX-B1423/20-Y-222688	2022. 7. 9	合格	

351	GX-B1423/20-Y-222689	2022. 7. 9	合格	 A yellow MT956L dump truck is parked on a dirt surface. Two workers wearing safety gear (hard hats, masks, and high-visibility vests) stand in front of the truck. The truck's license plate is 21-16. A yellow timestamp '2022/7/9' is visible in the bottom left corner of the photo.
352	GX-B1423/20-Y-222690	2022. 7. 9	合格	 Two yellow dump trucks are parked on a dirt surface. Two workers wearing safety gear (hard hats and high-visibility vests) stand between the trucks. A yellow timestamp '2022/7/9' is visible in the bottom right corner of the photo.

353	GX-B1423/20-Y-222691	2022. 7. 9	合格	
354	GX-B1423/20-Y-222692	2022. 7. 9	合格	

355	GX-B1423/20-Y-222693	2022. 7. 9	合格	
356	GX-B1423/20-Y-222694	2022. 7. 9	合格	

357	GX-B1423/20-Y-222695	2022. 7. 9	合格	
358	GX-B1423/20-Y-222696	2022年7月10日	合格	

359	GX-B1423/20-Y-222697	2022年7月10日	合格	 A yellow dump truck is parked on a dirt surface under a clear blue sky. Two workers wearing hard hats and safety vests are standing next to the truck. A yellow timestamp '2022/6/21' is visible in the bottom right corner of the photo.
360	GX-B1423/20-Y-222698	2022年7月10日	合格	 A yellow dump truck is parked on a dirt surface under a clear blue sky. Two workers wearing hard hats and safety vests are standing next to the truck, looking at a tablet. A yellow timestamp '2022/6/21' is visible in the bottom right corner of the photo.

361	GX-B1423/20-Y-222699	2022年7月10日	合格	 A yellow MT85 dump truck is parked on a dirt surface. Two workers, one in a grey uniform and red hard hat, and another in a green high-visibility vest and yellow hard hat, stand in front of the truck. The truck has 'MT85' and 'VTEC 4.0' visible on its side. A yellow timestamp '2022/8/21' is in the bottom right corner of the photo.
362	GX-B1423/20-Y-222700	2022年7月10日	合格	 A yellow MT85 dump truck is parked on a dirt surface. Two workers, one in a grey uniform and red hard hat, and another in a green high-visibility vest and yellow hard hat, stand in front of the truck. The truck has 'MT85' and 'VTEC 4.0' visible on its side. A yellow timestamp '2022/8/21' is in the bottom right corner of the photo.

363	GX-B1423/20-Y-222701	2022年7月10日	合格	
364	GX-B1423/20-Y-222702	2022年7月10日	合格	

365	GX-B1423/20-Y-222703	2022年7月10日	合格	
366	GX-B1423/20-Y-222704	2022年7月10日	合格	

367	GX-B1423/20-Y-222705	2022年7月10日	合格	 A yellow MT86H dump truck is shown from a side-front angle. Two workers in safety gear stand in front of the truck. The date stamp '2022/6/21' is visible in the bottom right corner of the photo.
368	GX-B1423/20-Y-222706	2022年7月10日	合格	 A yellow MT86H dump truck is shown from a front-three-quarter angle. Two workers in safety gear stand in front of the truck. The date stamp '2022/6/21' is visible in the bottom right corner of the photo.

369	GX-B1423/20-Y-222707	2022年7月10日	合格	
370	GX-B1423/20-Y-222708	2022年7月10日	合格	

371	GX-B1423/20-Y-222709	2022年7月10日	合格	
372	GX-B1423/20-Y-222710	2022年7月10日	合格	

373	GX-B1423/20-Y-222711	2022年7月10日	合格	
374	GX-B1423/20-Y-222712	2022年7月10日	合格	

375	GX-B1423/20-Y-222713	2022年7月10日	合格	
376	GX-B1423/20-Y-222714	2022年7月10日	合格	

377	GX-B1423/20-Y-222715	2022年7月10日	合格	
378	GX-B1423/20-Y-222716	2022年7月10日	合格	

379	GX-B1423/20-Y-222717	2022年7月10日	合格	
380	GX-B1423/20-Y-222718	2022年7月10日	合格	

381	GX-B1423/20-Y-222719	2022年7月10日	合格	
382	GX-B1423/20-Y-222720	2022年7月10日	合格	

383	GX-B1423/20-Y-222721	2022年7月10日	合格	
384	GX-B1423/20-Y-222722	2022年7月10日	合格	

385	GX-B1423/20-Y-222723	2022年7月10日	合格	
386	GX-B1423/20-Y-222724	2022年7月10日	合格	

387	GX-B1423/20-Y-222725	2022年7月10日	合格	
388	GX-B1423/20-Y-222726	2022年7月10日	合格	

389	GX-B1423/20-Y-222727	2022年7月10日	合格	
390	GX-B1423/20-Y-222728	2022年7月10日	合格	

391	GX-B1423/20-Y-222729	2022年7月10日	合格	
392	GX-B1423/20-Y-222730	2022年7月10日	合格	

393	GX-B1423/20-Y-222731	2022年7月10日	合格	
394	GX-B1423/20-Y-222732	2022年7月10日	合格	

395	GX-B1423/20-Y-222733	2022年7月10日	合格	
396	GX-B1423/20-Y-222734	2022年7月10日	合格	

397	GX-B1423/20-Y-222735	2022年7月10日	合格	
398	GX-B1423/20-Y-222736	2022年7月10日	合格	

399	GX-B1423/20-Y-222737	2022年7月10日	合格	
400	GX-B1423/20-Y-222738	2022年7月10日	合格	

401	GX-B1423/20-Y-222739	2022年7月10日	合格	
402	GX-B1423/20-Y-222740	2022年7月10日	合格	

403	GX-B1423/20-Y-222741	2022年7月10日	合格	
404	GX-B1423/20-Y-222742	2022年7月10日	合格	

405	GX-B1423/20-Y-222743	2022年7月10日	合格	
406	GX-B1423/20-Y-222744	2022年7月10日	合格	

407	GX-B1423/20-Y-222745	2022年7月10日	合格	
408	GX-B1423/20-Y-222746	2022年7月10日	合格	

409	GX-B1423/20-Y-222747	2022年7月10日	合格	
410	GX-B1423/20-Y-222748	2022年7月10日	合格	

411	GX-B1423/20-Y-222749	2022年7月10日	合格	
412	GX-B1423/20-Y-222750	2022年7月10日	合格	

413	GX-B1423/20-Y-222751	2022年7月10日	合格	
414	GX-B1423/20-Y-222752	2022年7月10日	合格	

415	GX-B1423/20-Y-222753	2022年7月10日	合格	
416	GX-B1423/20-Y-222754	2022年7月10日	合格	

417	GX-B1423/20-Y-222755	2022年7月10日	合格	
418	GX-B1423/20-Y-222756	2022年7月10日	合格	

419	GX-B1423/20-Y-222757	2022年7月10日	合格	
-----	----------------------	------------	----	---