

序号	报告编号	发布日期	结论	影像资料
1	GX-B1424/20-7-23001	2023. 2. 3	依据NB/T 10176-2019单轨吊车综合判定合格；依据MT/T 220-1990尾气所检项目合格。	
2	GX-B1424/20-7-23002	2023. 2. 3	依据NB/T 10176-2019单轨吊车综合判定合格；依据MT/T 220-1990尾气所检项目合格。	
3	GX-B1310/21-7-23001	2023. 2. 3	符合标准要求。	
4	GX-B1310/21-7-23002	2023. 2. 3	符合标准要求。	

5	GX-B1310/21-7-23003	2023. 2. 3	符合标准要求。			
6	GX-B1310/21-7-23004	2023. 2. 3	符合标准要求。			
7	GX-B1310/21-7-23005	2023. 2. 3	符合标准要求。			
8	GX-B1310/21-7-23006	2023. 2. 3	符合标准要求。			

9	GX-B1310/21-7-23007	2023. 2. 3	符合标准要求。			
10	GX-B1310/21-7-23008	2023. 2. 3	符合标准要求。			
11	GX-B1310/21-7-23009	2023. 2. 3	符合标准要求。			
12	GX-B1310/21-7-23010	2023. 2. 3	符合标准要求。			

13	GX-B1310/21-7-23011	2023. 2. 3	符合标准要求。			
14	GX-B1310/21-7-23012	2023. 2. 3	符合标准要求。			
15	GX-B1310/21-7-23013	2023. 2. 3	符合标准要求。			
16	GX-B1310/21-7-23014	2023. 2. 3	符合标准要求。			

17	GX-B1428/21-7- 22013	2023. 2. 3	无缺陷迹痕显示	
18	GX-B1428/21-7- 22014	2023. 2. 3	无缺陷迹痕显示	
19	GX-B1306/21-7-23001	2023. 2. 2	所检项目合格。	
20	GX-B1306/21-7-23002	2023. 2. 2	所检项目合格。	

21	GX-B1306/21-7-23003	2023. 2. 2	所检项目合格。	 A photograph showing two workers in a control room or office environment. They are standing near a large green control panel with various buttons and screens. The floor is green with red and white safety markings.
22	GX-B1306/21-7-23004	2023. 2. 2	所检项目合格。	 A photograph showing two workers in a control room. They are standing near a large green control panel. The floor is green with red and white safety markings.
23	GX-B1306/21-7-23005	2023. 2. 2	所检项目合格。	 A photograph showing two workers in a control room. They are standing near a large green control panel. The floor is green with red and white safety markings.
24	GX-B1312/20-7-23001	2023. 2. 6	所检项目合格。	 A photograph showing a worker wearing a red hard hat and a blue jacket, kneeling on the floor. The worker is using a blue toolbox and a red multimeter to inspect a piece of equipment. The equipment is red and has some cables attached to it.

25	GX-B1424/20-7-23003	2023. 2. 3	依据NB/T10176-2019单轨吊车所检项目合格。	
26	GX-B1517/20-7-23001	2023. 2. 8	综合判定：合格。	
27	GX-B1517/20-7-23002	2023. 2. 8	综合判定：合格。	
28	GX-B1517/20-7-23003	2023. 2. 8	综合判定：合格。	

29	GX-B1517/20-7-23004	2023. 2. 8	综合判定：合格。	
30	GX-B1517/20-7-23005	2023. 2. 8	综合判定：合格。	
31	GX-B1517/20-7-23006	2023. 2. 8	综合判定：合格。	
32	GX-B1517/20-7-23007	2023. 2. 8	综合判定：合格。	

33	GX-B1517/20-7-23008	2023. 2. 8	综合判定：合格。	
34	GX-B1310/21-7-23015	2023. 2. 3	符合标准要求	
35	GX-B1310/21-C-22058	2023. 2. 3	符合标准要求	
36	GX-B1310/21-C-22059	2023. 2. 3	符合标准要求	