

序号	报告编号	发布日期	结论	影像资料
1	GX-B1559/21-5-23011	2023/4/4	所检项目合格。	 <p>The first row of images shows a worker in a red helmet and grey uniform operating a piece of machinery. The left photo shows the worker's hands on the controls. The right photo shows a metal identification plate with the 'MA' logo and technical specifications, including the model 'ZL30E(B) 轮胎式防爆装载机'.</p>
2	GX-B1559/21-5-23012	2023/4/4	所检项目合格。	 <p>The second row of images shows a worker in a grey uniform operating a piece of machinery. The left photo shows the worker's hands on the steering wheel and controls. The right photo shows a metal identification plate with the 'MA' logo and technical specifications, including the model 'ZL30E(B) 轮胎式防爆装载机'.</p>

3	GX-B1321/20-5-23357~23359	2023/4/3	本次共检电力电缆3条，3条电力电缆所检项目合格。	 <p>2023年2月26日</p>
4	GX-B1495/20-5-23637~23641	2023/4/3	本次共检高压防爆开关5台，5台高压防爆开关所检项目合格。	 <p>2023年2月26日</p>

5	GX-B1416/22-5-23022	2023/4/4	综合判定:合格	
6	GX-B1310/21-5-23064	2023/4/6	未发现超过 $\Phi$ 2mm当量直径的缺陷。	
7	GX-B1310/21-5-23065	2023/4/6	符合标准要求	

8	GX-B1424/20-5-23005	2023/4/4	依据NB/T 10176-2019单轨吊车综合判定合格。	 <p>2023/3/16</p>
9	GX-B1424/20-5-23006	2023/4/4	依据NB/T 10176-2019单轨吊车所检项目合格。	 <p>2023/3/16</p>
10	GX-B1310/21-5-23051	2023/4/4	符合标准要求。	 <p>2023/3/16</p>

11	GX-B1416/22-5-23003	2023. 4. 3	综合判定：合格。	
12	GX-B1416/22-5-23004	2023. 4. 3	综合判定：合格。	
13	GX-B1416/22-5-23005	2023. 4. 3	综合判定：合格。	

14	GX-B1416/22-5-23006	2023. 4. 3	综合判定：合格。	
15	GX-B1416/22-5-23007	2023. 4. 3	综合判定：合格。	
16	GX-B1416/22-5-23017	2023. 4. 3	综合判定：合格。	

17	GX-B1416/22-5-23018	2023. 4. 3	综合判定：合格。	
18	GX-B1515/22-5-23006	2023年4月6日	合格	
19	GX-B1515/22-5-23007	2023年4月6日	合格	