

序号	报告编号	发布日期	结论	影像资料
386	GX-B1423/20-Y-221868	2022年5月9日	合格	 A photograph of a yellow MTB truck at a construction site. The truck is a large, heavy-duty vehicle with a dump body. The sun is visible in the upper left corner, creating a bright glare. A person in a grey uniform and a red hard hat is standing near the front of the truck. The background shows a hilly, rocky terrain. A yellow date stamp '2022/3/30' is located in the bottom right corner of the image.

387	GX-B1423/20-Y-221869	2022年5月9日	合格	
-----	----------------------	-----------	----	--

388	GX-B1423/20-Y-221870	2022年5月9日	合格	
-----	----------------------	-----------	----	---

389	GX-B1423/20-Y-221871	2022年5月9日	合格	
-----	----------------------	-----------	----	--

390	GX-B1423/20-Y-221872	2022年5月9日	合格	
-----	----------------------	-----------	----	--

391	GX-B1423/20-Y-221873	2022年5月9日	合格	 A photograph showing a worker in a white protective suit, red helmet, and blue face mask operating machinery. The worker is seated and focused on the task. A yellow timestamp '2022/3/30' is visible in the bottom right corner of the image.
-----	----------------------	-----------	----	--

392	GX-B1423/20-Y-221874	2022年5月9日	合格	
-----	----------------------	-----------	----	--

393	GX-B1423/20-Y-221875	2022年5月9日	合格	
-----	----------------------	-----------	----	--

394	GX-B1423/20-Y-221876	2022年5月9日	合格	
-----	----------------------	-----------	----	--

395	GX-B1423/20-Y-221877	2022年5月9日	合格	
-----	----------------------	-----------	----	--

396	GX-B1423/20-Y-221878	2022年5月9日	合格	
-----	----------------------	-----------	----	--

397	GX-B1423/20-Y-221879	2022年5月9日	合格	
-----	----------------------	-----------	----	--

398	GX-B1423/20-Y-221880	2022年5月9日	合格	
-----	----------------------	-----------	----	--

399	GX-B1423/20-Y-221881	2022年5月9日	合格	
-----	----------------------	-----------	----	--

400	GX-B1423/20-Y-221882	2022年5月9日	合格	
-----	----------------------	-----------	----	--

401	GX-B1423/20-Y-221883	2022年5月9日	合格	
-----	----------------------	-----------	----	--

402	GX-B1423/20-Y-221884	2022年5月9日	合格	
-----	----------------------	-----------	----	--

403	GX-B1423/20-Y-221885	2022年5月9日	合格	
-----	----------------------	-----------	----	--

404	GX-B1423/20-Y-221886	2022年5月9日	合格	
-----	----------------------	-----------	----	---

405	GX-B1423/20-Y-221887	2022年5月9日	合格	
-----	----------------------	-----------	----	--

406	GX-B1423/20-Y-221888	2022年5月9日	合格	 <p>A photograph of a yellow MT96L dump truck at a construction site. The truck is parked on a dirt surface, and several workers in safety gear are standing near the front. The truck has 'MT96L' and '2211' visible on its side. A yellow timestamp '2022/3/31' is in the bottom right corner of the photo.</p>
-----	----------------------	-----------	----	---

407	GX-B1423/20-Y-221889	2022年5月9日	合格	
-----	----------------------	-----------	----	--

408	GX-B1423/20-Y-221890	2022年5月9日	合格	
-----	----------------------	-----------	----	---

409	GX-B1423/20-Y-221891	2022年5月9日	合格	
-----	----------------------	-----------	----	--

410	GX-B1423/20-Y-221892	2022年5月9日	合格	
-----	----------------------	-----------	----	--

411	GX-B1423/20-Y-221893	2022年5月9日	合格	
-----	----------------------	-----------	----	--

412	GX-B1423/20-Y-221894	2022年5月9日	合格	
-----	----------------------	-----------	----	--

413	GX-B1423/20-Y-221895	2022年5月9日	合格	
-----	----------------------	-----------	----	---

414	GX-B1423/20-Y-221896	2022年5月9日	合格	
-----	----------------------	-----------	----	--

415	GX-B1423/20-Y-221897	2022年5月9日	合格	
-----	----------------------	-----------	----	--

416	GX-B1423/20-Y-221898	2022年5月9日	合格	 <p>A photograph showing a worker in a red hard hat and light-colored uniform operating a piece of machinery. The worker is seated on a black seat, holding the steering wheel. The machinery is white and grey. A yellow date stamp '2022/4/1' is visible in the bottom right corner of the photo.</p>
-----	----------------------	-----------	----	--

417	GX-B1423/20-Y-221899	2022年5月9日	合格	
-----	----------------------	-----------	----	--

418	GX-B1423/20-Y-221900	2022年5月9日	合格	
-----	----------------------	-----------	----	--

419	GX-B1423/20-Y-221901	2022年5月9日	合格	
-----	----------------------	-----------	----	---

420	GX-B1423/20-Y-221902	2022年5月9日	合格	
-----	----------------------	-----------	----	---

421	GX-B1423/20-Y-221903	2022年5月9日	合格	
-----	----------------------	-----------	----	--

422	GX-B1423/20-Y-221904	2022年5月9日	合格	
-----	----------------------	-----------	----	--

423	GX-B1423/20-Y-221905	2022年5月9日	合格	
-----	----------------------	-----------	----	--

424	GX-B1423/20-Y-221906	2022年5月9日	合格	
-----	----------------------	-----------	----	---

425	GX-B1423/20-Y-221907	2022年5月9日	合格	
-----	----------------------	-----------	----	--

426	GX-B1423/20-Y-221908	2022年5月9日	合格	
-----	----------------------	-----------	----	--

427	GX-B1423/20-Y-221909	2022年5月9日	合格	 <p>A photograph of a yellow MT56L dump truck at a construction site. A worker in a white uniform and red helmet stands in the foreground. The truck has 'MT56L' and '2216' visible on its side. A yellow timestamp '2022/4/2' is in the bottom right corner of the photo.</p>
-----	----------------------	-----------	----	--

428	GX-B1423/20-Y-221910	2022年5月9日	合格	
-----	----------------------	-----------	----	--

429	GX-B1423/20-Y-221911	2022年5月9日	合格	
-----	----------------------	-----------	----	--

430	GX-B1423/20-Y-221912	2022年5月9日	合格	
-----	----------------------	-----------	----	---

431	GX-B1423/20-Y-221913	2022年5月9日	合格	 A photograph showing a worker in a red hard hat and safety gear operating a piece of machinery. The worker is seated and appears to be adjusting or operating a control panel. The machinery is white and yellow. A yellow timestamp '2022/4/2' is visible in the bottom right corner of the photo.
-----	----------------------	-----------	----	---

432	GX-B1423/20-Y-221914	2022年5月9日	合格	
-----	----------------------	-----------	----	--

433	GX-B1423/20-Y-221915	2022年5月9日	合格	
-----	----------------------	-----------	----	--

434	GX-B1423/20-Y-221916	2022年5月9日	合格	 A photograph of a yellow MT96C truck, likely a mining or construction vehicle, parked on a dirt surface. A person in a white uniform and red helmet stands next to the truck. The truck has "MT96C" and "精工重机" (Seiko Heavy Machinery) written on its side. A yellow timestamp "2022-4-2" is visible in the bottom right corner of the photo.
-----	----------------------	-----------	----	--

435	GX-B1499/21-Y-22050	2022年5月8日	合格	
436	GX-B1499/21-Y-22051	2022年5月8日	合格	

437	GX-B1499/21-Y-22052	2022年5月8日	合格	
438	GX-B1499/21-Y-22053	2022年5月8日	合格	
439	GX-B1354/20-Y-22001	2022年5月7日	合格	
440	GX-B1517/20-Y-22001	2022年3月25日	合格	
441	GX-B1517/20-Y-22002	2022年3月25日	合格	

442	GX-B1521/20-Y-22105	2022年5月8号	合格	
443	GX-B1521/20-Y-22106	2022年5月8号	合格	

444	GX-B1521/20-Y-22107	2022年5月8号	合格	
445	GX-B1521/20-Y-22108	2022年5月8号	合格	

446	GX-B1521/20-Y-22109	2022年5月8号	合格	
447	GX-B1521/20-Y-22110	2022年5月8号	合格	

448	GX-B1521/20-Y-22111	2022年5月8号	合格	
449	GX-B1423/20-Y-221833	2022年5月8日	合格	

450	GX-B1423/20-Y-221834	2022年5月8日	合格	
451	GX-B1423/20-Y-221835	2022年5月8日	合格	

452	GX-B1423/20-Y-221836	2022年5月8日	合格	 <p>A close-up photograph of a worker wearing a red hard hat and a grey uniform, focused on operating a piece of heavy machinery. The worker's hands are on the steering wheel and controls. A yellow timestamp '2022/4/28' is visible in the bottom right corner of the image.</p>
453	GX-B1423/20-Y-221837	2022年5月8日	合格	 <p>A photograph of a large yellow truck with a white tank, labeled '洒水车' (Water Sprayer) in Chinese characters. Two workers in safety gear are standing in front of the truck. A yellow timestamp '2022/4/28' is visible in the bottom right corner of the image.</p>

454	GX-B1423/20-Y-221838	2022年5月8日	合格	
455	GX-B1423/20-Y-221839	2022年5月8日	合格	

456	GX-B1423/20-Y-221840	2022年5月8日	合格	
457	GX-B1423/20-Y-221841	2022年5月8日	合格	

458	GX-B1423/20-Y-221842	2022年5月8日	合格	
459	GX-B1423/20-Y-221843	2022年5月8日	合格	

460	GX-B1423/20-Y-221844	2022年5月8日	合格	
461	GX-B1423/20-Y-221845	2022年5月8日	合格	

462	GX-B1423/20-Y-221846	2022年5月8日	合格	 A close-up photograph of a worker wearing a red safety helmet and a grey work uniform, sitting in the driver's seat of a vehicle. The worker is holding the steering wheel and looking forward. A yellow timestamp '2022/4/28' is visible in the bottom right corner of the image.
463	GX-B1423/20-Y-221847	2022年5月8日	合格	 A photograph of a yellow water truck parked on a dirt surface. The truck has '27矿 洒水车' (27 Mine Water Sprayer) written on its side in red and blue characters. Two workers are standing in front of the truck: one in a red uniform and one in a grey uniform. A yellow timestamp '2022/4/28' is visible in the bottom right corner of the image.

464	GX-B1423/20-Y-221848	2022年5月8日	合格	 <p>A yellow XCMG XDR80T dump truck is parked in a quarry. Two workers in white protective suits and red hard hats stand in front of the truck. The truck has 'XCMG' and 'XDR80T' written on its side. A yellow timestamp '2022/4/28' is visible in the bottom right corner of the photo.</p>
465	GX-B1423/20-Y-221849	2022年5月8日	合格	 <p>A yellow XCMG dump truck is shown from a front-quarter view. A worker in a white protective suit and red hard hat is standing next to the truck, pointing at the front. The truck has 'XCMG' on the hood and '876' on the front panel. A yellow timestamp '2022/4/28' is visible in the bottom right corner of the photo.</p>

466	GX-B1423/20-Y-221850	2022年5月8日	合格	
467	GX-B1423/20-Y-221851	2022年5月8日	合格	

468	GX-B1423/20-Y-221852	2022年5月8日	合格	
469	GX-B1423/20-Y-221853	2022年5月8日	合格	

470	GX-B1423/20-Y-221854	2022年5月8日	合格	
471	GX-B1423/20-Y-221855	2022年5月8日	合格	

472	GX-B1423/20-Y-221856	2022年5月8日	合格	 <p>A photograph of a yellow XDR80T truck. Two workers wearing red hard hats and safety vests are standing in front of the truck. The truck has 'XDR80T' and 'ELECTRIC' written on its side. A yellow timestamp '2022/4/28' is visible in the bottom right corner of the image.</p>
473	GX-B1423/20-Y-221857	2022年5月8日	合格	 <p>A photograph showing a worker in a red hard hat and safety vest standing next to a yellow truck. Another worker is visible in the driver's seat. The background shows a construction site with hills. A yellow timestamp '2022/4/28' is visible in the bottom right corner of the image.</p>

474	GX-B1423/20-Y-221858	2022年5月8日	合格	
475	GX-B1423/20-Y-221859	2022年5月8日	合格	

476	GX-B1423/20-Y-221860	2022年5月8日	合格	
477	GX-B1423/20-Y-221861	2022年5月8日	合格	

478	GX-B1423/20-Y-221862	2022年5月8日	合格	
479	GX-B1423/20-Y-221863	2022年5月8日	合格	

480	GX-B1423/20-Y-221864	2022年5月8日	合格	
481	GX-B1423/20-Y-221865	2022年5月8日	合格	

482	GX-B1423/20-Y-221866	2022年5月8日	合格	
483	GX-B1423/20-Y-221867	2022年5月8日	合格	

484	GX-B1539/20-Y-22064	2022年5月8号	合格	
485	GX-B1539/20-Y-22065	2022年5月8号	合格	


486	GX-B1539/20-Y-22066	2022年5月8号	合格	
487	GX-B1539/20-Y-22067	2022年5月8号	合格	

488	GX-B1521/20-Y-22112	2022年5月8号	合格	 <p>A yellow excavator is shown in operation at a construction site. The excavator is positioned on a dirt ground, and its bucket is raised. In the background, there is a large pile of rubble and debris, suggesting a demolition or earthmoving project. The sky is clear and blue. A yellow timestamp '2022/5/8' is visible in the bottom right corner of the image.</p>
489	GX-B1521/20-Y-22113	2022年5月8号	合格	 <p>A worker wearing a red hard hat and safety gear is shown operating machinery. The worker is seated and appears to be focused on the task. The background shows the interior of a vehicle or piece of equipment. A yellow timestamp '2022/5/8' is visible in the bottom right corner of the image.</p>

490	GX-B1521/20-Y-22114	2022年5月8号	合格	 <p>A close-up photograph of the operator's cab of a yellow SANY excavator. The cab is made of metal and has a large glass window. The SANY logo is visible on the side of the cab. The background is a clear blue sky. A yellow timestamp '2022/4/3' is visible in the bottom right corner of the image.</p>
491	GX-B1521/20-Y-22115	2022年5月8号	合格	 <p>A photograph of a yellow SANY 5 excavator operating on a construction site. The excavator is shown from a side profile, with its arm and bucket raised. A worker in a red hard hat and white shirt is standing next to the excavator. The background shows a blue fence and a clear sky. A yellow timestamp '2022/4/3' is visible in the bottom right corner of the image.</p>


492	GX-B1521/20-Y-22116	2022年5月8号	合格	
493	GX-B1521/20-Y-22117	2022年5月8号	合格	

494	GX-B1521/20-Y-22118	2022年5月8号	合格	 <p>A close-up photograph of a worker wearing a blue hard hat and work clothes, operating a piece of machinery. The worker is focused on the task, and the machinery is partially visible. A yellow timestamp '2022/4/3' is visible in the bottom right corner of the image.</p>
495	GX-B1521/20-Y-22119	2022年5月8号	合格	 <p>A photograph of a yellow excavator at a construction site. The excavator is positioned on a dirt surface, and its arm is extended. In the background, there are other pieces of machinery and a cloudy sky. A yellow timestamp '2022/4/3' is visible in the bottom right corner of the image.</p>

496	GX-B1312/20-Y-22093~22095	2022年5月8日	合格	
-----	---------------------------	-----------	----	---

497	GX-B1312/20-Y-22096~22097	2022年5月8日	合格	
-----	---------------------------	-----------	----	---

498	X-B1495/20-Y-22246~22259	2022年5月8日	合格	
-----	--------------------------	-----------	----	---

499	GX-B1495/20-Y-22260~22273	2022年5月8日	合格	
-----	---------------------------	-----------	----	---

500	GX-B1495/20-Y-22274~22283	2022年5月8日	合格	
-----	---------------------------	-----------	----	---

501	GX-B1499/21-Y-22054	2022年5月8日	合格	
-----	---------------------	-----------	----	---

502	GX-B1499/21-Y-22055	2022年5月8日	合格	
-----	---------------------	-----------	----	---

503	GX-B1499/21-Y-22056	2022年5月8日	合格	
-----	---------------------	-----------	----	---

504	GX-B1381/20-Y-22006	2022年5月8日	合格	
-----	---------------------	-----------	----	---