

序号	报告编号	发布日期	结论	影像资料
903	GX-B1306/21-Y-22049	2022年5月19日	合格	

904	GX-B1306/21-Y-22050	2022年5月19日	合格	
-----	---------------------	------------	----	---

905	GX-B1308/21-Y-22008 GX-B1499/21-Y-22067 GX-B1499/21-Y-22068 GX-B1499/21-Y-22069	2022年5月18日	合格	
-----	--	------------	----	---

906	GX-B1499/21-Y-22070 GX-B1499/21-Y-22071	2022年5月18日	合格	
-----	--	------------	----	---

907	GX-B1423/20-Y-222143	2022年5月18日	合格	
908	GX-B1423/20-Y-222144	2022年5月18日	合格	

909	GX-B1423/20-Y-222145	2022年5月18日	合格	
910	GX-B1423/20-Y-222146	2022年5月18日	合格	

911	GX-B1423/20-Y-222147	2022年5月18日	合格	 <p>A photograph of a yellow TONLY dump truck. Two workers are standing in front of the truck. One worker is wearing a light blue uniform and a red hard hat, while the other is wearing a dark jacket and a black hard hat. The truck has 'TONLY' written on its side. The photo includes a watermark 'Shot on X27 vivo AI camera' and a date stamp '2022/4/13'.</p>
912	GX-B1423/20-Y-222148	2022年5月18日	合格	 <p>A photograph showing a worker in a light blue uniform and a red hard hat inspecting a yellow dump truck. The worker is standing in front of the truck, looking at the front. The truck is parked in an open area with hills in the background. The photo includes a date stamp '2022/4/13'.</p>

913	GX-B1423/20-Y-222149	2022年5月18日	合格	
914	GX-B1423/20-Y-222150	2022年5月18日	合格	

915	GX-B1423/20-Y-222151	2022年5月18日	合格	 <p>A photograph showing a yellow Mitsui truck with license plate Q032. Two men are standing in front of the truck. The man on the left is wearing a grey work uniform and a red hard hat. The man on the right is wearing a dark jacket and a purple shirt. The background shows a desert landscape with mountains. A yellow timestamp '2022/4/13' is visible in the bottom right corner of the photo.</p>
916	GX-B1423/20-Y-222152	2022年5月18日	合格	 <p>A photograph showing a yellow Mitsui truck with license plate Q052. A man in a grey work uniform and a red hard hat is standing next to the truck, looking at it. The background shows a desert landscape with mountains. A yellow timestamp '2022/4/13' is visible in the bottom right corner of the photo.</p>


917	GX-B1423/20-Y-222153	2022年5月18日	合格	 <p>A photograph of a yellow MT96L dump truck parked on a dirt surface. Two workers in safety gear are standing in front of the truck. The truck has 'MT96L' and '三一重工' (Sany Heavy Industry) branding. A yellow timestamp '2022/4/13' is visible in the bottom right corner of the image.</p>
918	GX-B1423/20-Y-222154	2022年5月18日	合格	 <p>A photograph showing a worker in a red hard hat and light-colored work clothes operating a yellow machine from the driver's seat. The worker is holding a handheld device. A yellow timestamp '2022/4/13' is visible in the bottom right corner of the image.</p>

919	GX-B1423/20-Y-222155	2022年5月18日	合格	 <p>A yellow MT58L dump truck is parked on a dirt surface at a construction site. A worker in a red hard hat and grey uniform is standing next to the truck, pointing towards it. The truck has 'MT58L' written on the top of the cab. A yellow timestamp '2022/4/13' is visible in the bottom right corner of the photo.</p>
920	GX-B1521/20-Y-22145	2022年5月16日	合格	 <p>A yellow S016 excavator is shown at a construction site. The excavator's arm is raised, and its bucket is positioned over a pile of dirt. A worker in a red hard hat and grey uniform is standing near the excavator. The background shows a hilly landscape under a clear blue sky. A yellow timestamp '2022/4/13' is visible in the bottom right corner of the photo.</p>

921	GX-B1521/20-Y-22146	2022年5月16日	合格	 <p>A yellow tracked loader with 'SDLG' branding is shown in a construction or mining environment. A worker in a red hard hat and grey uniform is standing on the machine. The background shows a dirt area and a hillside. A yellow timestamp '2022/4/13' is visible in the bottom right corner of the photo.</p>
922	GX-B1539/20-Y-22083	2022年5月18日	合格	 <p>Two workers are standing in front of a yellow wheel loader with 'SEM' and '652D' branding. One worker is wearing a red hard hat and a grey uniform, while the other is in a dark blue jacket. They appear to be reviewing a document. The background shows a dirt area and a hillside. A yellow timestamp '2022/4/13' is visible in the bottom right corner of the photo.</p>

923	GX-B1499/21-Y-22064	2022年5月19日	/	
924	GX-B1499/21-Y-22065	2022年5月19日	/	

925	GX-B1499/21-Y-22066	2022年5月19日	/	 A worker wearing a red hard hat and a grey uniform is kneeling on rocks by a river. He is working on a large, dark pipe. A yellow pipe is visible in the foreground. The background shows a rocky riverbank. A yellow timestamp '2022/4/14' is in the bottom right corner.
926	GX-B1312/20-Y-22100	2022年5月19日	合格	 Two workers in red hard hats are on a utility structure. One worker is standing on a platform, and the other is below. A large metal box is mounted on the structure. The background shows a dry, hilly landscape. A yellow timestamp '2022/4/14' is in the bottom left corner.

927	GX-B1312/20-Y-22101	2022年5月19日	合格	
-----	---------------------	------------	----	---

928	GX-B1423/20-Y-222192 GX-B1423/20-Y-222193	2022年5月17日	合格	 
-----	--	------------	----	---



929	GX-B1423/20-Y-222194 GX-B1423/20-Y-222195	2022年5月17日	合格	 
-----	--	------------	----	---

930	GX-B1423/20-Y-222196 GX-B1423/20-Y-222197	2022年5月17日	合格	 
-----	--	------------	----	--



931	GX-B1423/20-Y-222198 GX-B1423/20-Y-222199	2022年5月17日	合格	
-----	--	------------	----	--

932	GX-B1423/20-Y-222200 GX-B1423/20-Y-222201	2022年5月17日	合格	 
-----	--	------------	----	---



933	GX-B1423/20-Y-222202 GX-B1423/20-Y-222203	2022年5月17日	合格	 
-----	--	------------	----	---



934	GX-B1423/20-Y-222204 GX-B1423/20-Y-222205	2022年5月17日	合格	 
-----	--	------------	----	---



935	GX-B1423/20-Y-222206 GX-B1423/20-Y-222207	2022年5月17日	合格	 
-----	--	------------	----	---



936	GX-B1423/20-Y-222208 GX-B1423/20-Y-222209	2022年5月17日	合格	 
-----	--	------------	----	---



937	GX-B1423/20-Y-222210	2022年5月17日	合格	
-----	----------------------	------------	----	---

938	GX-B1381/20-Y-22008	2022年5月20日	合格	
-----	---------------------	------------	----	---

939	GX-B1310/21-Y-22036 GX-B1310/21-Y-22037 GX-B1310/21-Y-22038 GX-B1310/21-Y-22039 GX-B1310/21-Y-22040 GX-B1310/21-Y-22041	2022年5月20日	合格	
-----	--	------------	----	---

940	GX-B1428/21-Y-22040 GX-B1428/21-Y-22041	2022年5月20日	合格	
-----	--	------------	----	---

941	GX-B1423/20-Y-222211 GX-B1423/20-Y-222212	2022年5月20日	合格	 
-----	--	------------	----	---

942	GX-B1423/20-Y-222213 GX-B1423/20-Y-222214	2022年5月20日	合格	
-----	--	------------	----	---

943	GX-B1423/20-Y-222215 GX-B1423/20-Y-222216	2022年5月20日	合格	 
-----	--	------------	----	--

944	GX-B1423/20-Y-222217 GX-B1423/20-Y-222218	2022年5月20日	合格	
-----	--	------------	----	---

945	GX-B1423/20-Y-222219 GX-B1423/20-Y-222220	2022年5月20日	合格	 
-----	--	------------	----	--



946	GX-B1423/20-Y-222221 GX-B1423/20-Y-222222	2022年5月20日	合格	 
-----	--	------------	----	--



947	GX-B1423/20-Y-222223 GX-B1423/20-Y-222224	2022年5月20日	合格	 
-----	--	------------	----	--



948	GX-B1423/20-Y-222225 GX-B1423/20-Y-222226	2022年5月20日	合格	
-----	--	------------	----	---

949	GX-B1423/20-Y-222227 GX-B1423/20-Y-222228	2022年5月20日	合格	 
-----	--	------------	----	--



950	GX-B1423/20-Y-222229 GX-B1423/20-Y-222230	2022年5月20日	合格	
-----	--	------------	----	---

951	GX-B1423/20-Y-222231 GX-B1423/20-Y-222232	2022年5月20日	合格	 
-----	--	------------	----	--



952	GX-B1423/20-Y-222233 GX-B1423/20-Y-222234	2022年5月20日	合格	
-----	--	------------	----	---

953	GX-B1423/20-Y-222235 GX-B1423/20-Y-222236	2022年5月20日	合格	 
-----	--	------------	----	---

954	GX-B1423/20-Y-222237 GX-B1423/20-Y-222238	2022年5月20日	合格	
-----	--	------------	----	---

955	GX-B1423/20-Y-222239 GX-B1423/20-Y-222240	2022年5月20日	合格	
-----	--	------------	----	---

956	GX-B1423/20-Y-222241 GX-B1423/20-Y-222242	2022年5月20日	合格	 
-----	--	------------	----	--



957	GX-B1423/20-Y-222243 GX-B1423/20-Y-222244	2022年5月20日	合格	
-----	--	------------	----	---

958	GX-B1423/20-Y-222245 GX-B1423/20-Y-222246	2022年5月20日	合格	 
-----	--	------------	----	--



959	GX-B1423/20-Y-222247 GX-B1423/20-Y-222248	2022年5月20日	合格	
-----	--	------------	----	---

960	GX-B1423/20-Y-222249 GX-B1423/20-Y-222250	2022年5月20日	合格	 
-----	--	------------	----	--



961	GX-B1423/20-Y-222301	2022年5月19日	合格	
962	GX-B1423/20-Y-222302	2022年5月19日	合格	

963	GX-B1423/20-Y-222303	2022年5月19日	合格	 A yellow dump truck with the number 218 on its side is parked on a dirt road. Two workers in white protective suits and hard hats are standing next to it. The truck has 'TONLY' written on the side. A yellow timestamp '2022/4/2' is visible in the bottom right corner of the photo.
964	GX-B1423/20-Y-222304	2022年5月19日	合格	 A yellow dump truck with the number 208 on its side is parked on a dirt road. Two workers in white protective suits and hard hats are standing next to it. The truck has '208' written on the side. A yellow timestamp '2022/4/2' is visible in the bottom right corner of the photo.

965	GX-B1423/20-Y-222305	2022年5月19日	合格	
966	GX-B1423/20-Y-222306	2022年5月19日	合格	

967	GX-B1423/20-Y-222307	2022年5月19日	合格	
968	GX-B1423/20-Y-222308	2022年5月19日	合格	

969	GX-B1423/20-Y-222309	2022年5月19日	合格	
970	GX-B1423/20-Y-222310	2022年5月19日	合格	

971	GX-B1423/20-Y-222311	2022年5月19日	合格	
972	GX-B1423/20-Y-222312	2022年5月19日	合格	

973	GX-B1423/20-Y-222313	2022年5月19日	合格	
974	GX-B1423/20-Y-222314	2022年5月19日	合格	

975	GX-B1423/20-Y-222315	2022年5月19日	合格	
976	GX-B1423/20-Y-222316	2022年5月19日	合格	

977	GX-B1423/20-Y-222317	2022年5月19日	合格	
978	GX-B1423/20-Y-222318	2022年5月19日	合格	

979	GX-B1423/20-Y-222319	2022年5月19日	合格	
980	GX-B1423/20-Y-222320	2022年5月19日	合格	

981	GX-B1423/20-Y-222321	2022年5月19日	合格	
982	GX-B1423/20-Y-222322	2022年5月19日	合格	

983	GX-B1423/20-Y-222323	2022年5月19日	合格	
984	GX-B1423/20-Y-222324	2022年5月19日	合格	

985	GX-B1423/20-Y-222325	2022年5月19日	合格	
986	GX-B1423/20-Y-222326	2022年5月19日	合格	

987	GX-B1423/20-Y-222327	2022年5月19日	合格	 <p>A yellow dump truck is parked on a dirt surface. Two workers wearing hard hats and safety gear are standing in front of the truck. The truck's bed is raised. A yellow timestamp '2022/4/3' is visible in the bottom right corner of the photo.</p>
988	GX-B1423/20-Y-222328	2022年5月19日	合格	 <p>A yellow dump truck with the number '122' on the front bumper is parked on a dirt surface. Two workers wearing hard hats and safety gear are standing near a large pile of rocks. The truck's bed is raised. A yellow timestamp '2022/4/3' is visible in the bottom right corner of the photo.</p>

989	GX-B1423/20-Y-222329	2022年5月19日	合格	
990	GX-B1423/20-Y-222330	2022年5月19日	合格	

991	GX-B1423/20-Y-222331	2022年5月19日	合格	 A photograph showing a worker wearing a red hard hat, a grey uniform, and a blue face mask. The worker is seated in the driver's seat of a yellow dump truck, looking at a handheld device. The truck is parked outdoors, and the background shows a clear sky and some distant structures. A yellow timestamp '2022/4/4' is visible in the bottom right corner of the image.
992	GX-B1423/20-Y-222332	2022年5月19日	合格	 A photograph of a yellow dump truck parked in a quarry or mining site. Two workers in grey uniforms and hard hats are standing in front of the truck. The truck is a large, heavy-duty vehicle with a high dump body. The background shows rocky terrain and a clear sky. A yellow timestamp '2022/4/4' is visible in the bottom right corner of the image.

993	GX-B1423/20-Y-222333	2022年5月19日	合格	 <p>A photograph showing a yellow mining truck parked on a dirt surface. Two workers wearing hard hats and safety gear are standing to the right of the truck, one holding a clipboard. The background shows a construction site with a pile of rocks and a clear sky. A yellow timestamp '2022/4/4' is visible in the bottom right corner of the image.</p>
994	GX-B1423/20-Y-222334	2022年5月19日	合格	 <p>A photograph of a large industrial structure, likely a conveyor belt system, with a worker standing in front of it. The structure is dark and has a complex, angular design. A bright light source is visible in the upper left, creating a lens flare. A yellow timestamp '2022/4/4' is visible in the bottom right corner of the image.</p>

995	GX-B1423/20-Y-222335	2022年5月19日	合格	
996	GX-B1423/20-Y-222336	2022年5月19日	合格	

997	GX-B1423/20-Y-222337	2022年5月19日	合格	
998	GX-B1423/20-Y-222338	2022年5月19日	合格	

999	GX-B1423/20-Y-222339	2022年5月19日	合格	 <p>A yellow dump truck with '徐工集团' (Xuchong Group) written on its side. Two workers in safety gear stand in front of the truck. A yellow timestamp '2022/4/4' is visible in the bottom right corner of the photo.</p>
1000	GX-B1423/20-Y-222340	2022年5月19日	合格	 <p>A yellow dump truck with '徐工集团' (Xuchong Group) written on its side. A worker in safety gear stands next to the truck. A yellow timestamp '2022/4/4' is visible in the bottom right corner of the photo.</p>

1001	GX-B1423/20-Y-222341	2022年5月19日	合格	
1002	GX-B1423/20-Y-222342	2022年5月19日	合格	

1003	GX-B1423/20-Y-222343	2022年5月19日	合格	
1004	GX-B1423/20-Y-222344	2022年5月19日	合格	

1005	GX-B1423/20-Y-222345	2022年5月19日	合格	
1006	GX-B1423/20-Y-222346	2022年5月19日	合格	

1007	GX-B1423/20-Y-222347	2022年5月19日	合格	
1008	GX-B1423/20-Y-222348	2022年5月19日	合格	

1009	GX-B1423/20-Y-222349	2022年5月19日	合格	
1010	GX-B1423/20-Y-222350	2022年5月19日	合格	

1011	GX-B1423/20-Y-222351	2022年5月19日	合格	
1012	GX-B1423/20-Y-222352	2022年5月19日	合格	

1013	GX-B1423/20-Y-222353	2022年5月19日	合格	 <p>A worker wearing a white protective suit, a red hard hat, and a blue face mask is seated in the operator's seat of a piece of heavy machinery, possibly a loader or excavator. The worker is looking towards the camera. A yellow timestamp '2022/5/19' is visible in the bottom right corner of the photo.</p>
1014	GX-B1423/20-Y-222354	2022年5月19日	合格	 <p>Two workers wearing red hard hats and face masks are standing in front of a large yellow dump truck. One worker is wearing a white protective suit, and the other is wearing a dark jacket. A yellow timestamp '2022/4/4' is visible in the bottom right corner of the photo.</p>

1015	GX-B1423/20-Y-222355	2022年5月19日	合格	 <p>2022/4/4</p>
1016	GX-B1423/20-Y-222356	2022年5月19日	合格	 <p>2022/4/4</p>

1017	GX-B1423/20-Y-222357	2022年5月19日	合格	
1018	GX-B1521/20-Y-22158	2022年5月20日	合格	

1019	GX-B1521/20-Y-22159	2022年5月20日	合格	 A yellow XCMG excavator is shown in a quarry setting. A person in a white shirt and red hard hat is standing next to the machine. The background shows a large pile of rocks and a hillside. A yellow timestamp '2022/4/4' is visible in the bottom right corner of the photo.
1020	GX-B1521/20-Y-22160	2022年5月20日	合格	 A yellow XCMG XE470D excavator is shown in a quarry setting. The machine is positioned on a rocky slope. A person in a white shirt and red hard hat is visible near the machine. The background shows a large pile of rocks and a hillside. A yellow timestamp '2022/4/4' is visible in the bottom right corner of the photo.

1021	GX-B1521/20-Y-22161	2022年5月20日	合格	 A yellow tracked excavator with the number '5' on its side is shown in a quarry or construction site. A person in a white uniform and red helmet stands next to the machine. The background shows a rocky hillside. A yellow timestamp '2022/4/4' is visible in the bottom right corner of the photo.
1022	GX-B1521/20-Y-22162	2022年5月20日	合格	 A yellow tracked excavator with the number '6' on its side is shown in a quarry or construction site. A person in a white uniform and red helmet stands next to the machine. The background shows a rocky hillside. A yellow timestamp '2022/4/4' is visible in the bottom right corner of the photo.

1023	GX-B1521/20-Y-22163	2022年5月20日	合格	
1024	GX-B1521/20-Y-22164	2022年5月20日	合格	

1025	GX-B1521/20-Y-22165	2022年5月20日	合格	
1026	GX-B1521/20-Y-22166	2022年5月20日	合格	

1027	GX-B1521/20-Y-22167	2022年5月20日	合格	
1028	GX-B1539/20-Y-22088	2022年5月19日	合格	

1029	GX-B1539/20-Y-22089	2022年5月19日	合格	
1030	GX-B1539/20-Y-22090	2022年5月19日	合格	

1031	GX-B1531/20-Y-22458-22502	2022年5月17日	合格	
------	---------------------------	------------	----	---

1032	GX-B1531/20-Y-22414-22457	2022年5月17日	合格	
------	---------------------------	------------	----	---

1033	GX-B1531/20-Y-22503-22543	2022年5月17日	合格	
------	---------------------------	------------	----	---

1034	GX-B1350/21-Y-22001 GX-B1350/21-Y-22002 GX-B1350/21-Y-22003 GX-B1350/21-Y-22004	2022年5月20日	合格	 A photograph showing a worker in a high-visibility yellow vest and a red hard hat working on electrical equipment. The worker is holding a device, possibly a multimeter, and is surrounded by wires and components. The date '2022/5/10' is visible in the bottom right corner of the photo.
------	--	------------	----	---