

序号	报告编号	发布日期	结论	影像资料
121	GX-B1310/21-3-25048	2025年3月13日	符合标准要求。	 A photograph showing a worker in a red hard hat, safety glasses, and a high-visibility vest inspecting a structure. The worker is kneeling and looking at a vertical metal beam. The date '2025.3.10' is visible in the bottom right corner of the photo.
122	GX-B1428/21-3-25016	2025年3月13日	无缺陷迹痕显示。	 A photograph showing a worker in a red hard hat, safety glasses, and a high-visibility vest inspecting a structure. The worker is standing and looking at a vertical metal beam. The date '2025.03.10' is visible in the bottom right corner of the photo.

123	GX-B1451/20-3-25112~25117	2025年3月14日	本次共检高压开关设备6台，6台高压开关设备所检项目合格。	 A photograph showing a worker in a red uniform and red helmet working on electrical equipment. The worker is standing in a control room or similar environment. The date '2025.03.01' is visible in the bottom right corner of the photo.
124	GX-B1322/21-3-25061~25064	2025年3月17日	本次共检电力电缆4条，4条电力电缆所检项目合格。	 A photograph showing a worker in a yellow safety vest and red helmet working on a large orange pipe. The worker is using a tool to inspect the pipe. The date '2025.03.06' is visible in the bottom right corner of the photo.

125	GX-B1322/21-3-25065~25071	2025年3月17日	本次共检电力电缆7条，7条电力电缆所检项目合格。	 <p>2025.03.07</p>
126	GX-B1322/21-3-25072~25076	2025年3月17日	本次共检电力电缆5条，5条电力电缆所检项目合格。	 <p>2025.03.08</p>

127	GX-B1451/20-3-25119	2025年3月17日	所检项目合格。	 <p>2025.03.06</p>
128	GX-B1451/20-3-25120~25122	2025年3月17日	本次共检高压开关柜3台，3台高压开关柜所检项目合格。 。	 <p>2025.03.07</p>

129	GX-B1451/20-3-25123~25124	2025年3月17日	本次共检高压开关柜2台，2台高压开关柜所检项目合格。 。	
130	GX-B1451/20-3-25125~25128	2025年3月17日	本次共检高压开关柜4台，4台高压开关柜所检项目合格。 。	

131	GX-B1310/21-3-25046	2025年3月19日	符合标准要求。	
132	GX-B1427/21-3-25014	2025年3月19日	符合标准要求。	

133	GX-B1310/21-3-25047	2025年3月19日	符合标准要求。	
134	GX-B1427/21-3-25015	2025年3月19日	符合标准要求。	

135	GX-B1428/21-3-25017	2025年3月19日	无缺陷痕迹显示。	 <p>2025.3.9</p>
136	GX-B1313/21-3-25029~25034	2025年3月18日	本次共检电力变压器6台，6台电力变压器所检项目合格。	 <p>2025.03.06</p>

137	GX-B1313/21-3-25035~25038	2025年3月18日	本次共检电力变压器4台，4台电力变压器所检项目合格。	
138	GX-B1313/21-3-25039	2025年3月18日	所检项目合格。	

139	GX-B1313/21-3-25040~25042	2025年3月18日	本次共检电力变压器3台，3台电力变压器所检项目合格。	 A photograph showing a worker in a red helmet and high-visibility vest working on a transformer. The worker is holding a tool and looking at the equipment. The date 2025.03.08 is visible in the bottom right corner of the image.
140	GX-B1520/20-3-25001	2025年3月18日	所检项目合格。	 A photograph showing a worker in a red helmet and high-visibility vest standing next to a large blue transformer. The worker is holding a tool and looking at the equipment. The date 2025.03.08 is visible in the bottom right corner of the image.

141	GX-B1520/20-3-25002	2025年3月18日	所检项目合格。	
142	GX-B1328/20-3-25041~25042	2025年3月19日	本次共检绝缘手套16只、绝缘靴12只，16只绝缘手套、12只绝缘靴合格。	

143	GX-B1328/20-3-25043~25045	2025年3月19日	本次共验电器3个、绝缘杆4套、携带式接地和接地短路装置4套，3个验电器、4套绝缘杆、4套携带式接地和接地短路装置合格。	 <p>2025.03.08</p>
144	GX-B1328/20-3-25046	2025年3月19日	本次共检绝缘胶垫80件，80件绝缘胶垫合格。	 <p>2025.03.08</p>