

序号	报告编号	发布日期	结论	影像资料
1	GX-B1329/21-5-25001~25002	2025. 4. 2	本次共检氧化锌避雷器2组，2组所检项目合格。	
2	GX-B1451/20-5-25002~25019	2025. 4. 3	本次共检高压开关柜18台，18台高压开关柜所检项目合格。	


3	GX-B1451/20-5-25020~25025	2025. 4. 3	本次共检高压开关柜6台, 6台高压开关柜所检项目合格。	
4	GX-B1451/20-5-25026~25034	2025. 4. 3	本次共检高压开关柜9台, 9台高压开关柜所检项目合格。	

5	GX-B1451/20-5-25035~25049	2025. 4. 3	本次共检高压开关柜15台, 15台高压开关柜所检项目合格。	
6	GX-B1451/20-5-25050~25052	2025. 4. 3	本次共检高压开关柜3台, 3台高压开关柜所检项目合格。	

7	GX-B1451/20-5-25053~25072	2025. 4. 3	本次共检高压开关柜20台, 20台高压开关柜所检项目合格。		
8	GX-B1451/20-5-25073~25079	2025. 4. 3	本次共检高压开关柜7台, 7台高压开关柜所检项目合格。		

9	GX-B1451/20-5-25080~25087	2025. 4. 3	本次共检高压开关柜8台, 8台高压开关柜所检项目合格。	 <p>2025/3/31</p>
10	GX-B1451/20-5-25088~25091	2025. 4. 3	本次共检高压开关柜4台, 4台高压开关柜所检项目合格。	 <p>2025/3/31</p>

11	GX-B1451/20-5-25092~25105	2025. 4. 3	本次共检高压开关柜14台, 14台高压开关柜所检项目合格。	 A photograph showing two workers in red hard hats and dark clothing inspecting a row of high-voltage switchgear. One worker is kneeling and looking at a device on the floor, while the other stands nearby. The date stamp '2025/3/31' is visible in the bottom right corner of the photo.
12	GX-B1313/21-5-25001~25002	2025. 4. 3	本次共检电力变压器2台, 2台电力变压器所检项目合格。	 A photograph showing a worker in a red hard hat and dark clothing inspecting a power transformer. The worker is standing next to a large, light-colored transformer unit. The date stamp '2025/3/28' is visible in the bottom right corner of the photo.

13	GX-B1313/21-5-25003~25004	2025. 4. 3	本次共检电力变压器2台，2台电力变压器所检项目合格。	
14	GX-B1313/21-5-25005~25013	2025. 4. 3	本次共检电力变压器9台，9台电力变压器所检项目合格。	


15	GX-B1313/21-5-25014	2025. 4. 3	所检项目合格。			
16	GX-B1313/21-5-25015~25020	2025. 4. 3	本次共检电力变压器6台，6台电力变压器所检项目合格。			

17	GX-B1313/21-5-25021~25025	2025. 4. 3	本次共检电力变压器5台，5台电力变压器所检项目合格。	
18	GX-B1313/21-5-25026~25029	2025. 4. 3	本次共检电力变压器4台，4台电力变压器所检项目合格。	


19	GX-B1322/21-5-25116~25120	2025. 4. 3	本次共检电力电缆5条，5条电力电缆所检项目合格。		
20	GX-B1322/21-5-25121~25125	2025. 4. 3	本次共检电力电缆5条，5条电力电缆所检项目合格。		

21	GX-B1322/21-5-25126~25131	2025. 4. 3	本次共检电力电缆6条，6条电力电缆所检项目合格。	
22	GX-B1322/21-5-25132~25139	2025. 4. 3	本次共检电力电缆8条，8条电力电缆所检项目合格。	

23	GX-B1350/21-5-25001	2025. 4. 2	本次共检验接地装置9处，9处接地装置所检项目合格。	
24	GX-B1350/21-5-25002	2025. 4. 2	本次共检验接地装置12处，12处接地装置所检项目合格。	

25	GX-B1350/21-5-25003	2025. 4. 2	本次共检验接地装置13处，13处接地装置所检项目合格。			
26	GX-B1350/21-5-25004	2025. 4. 2	本次共检验接地装置13处，13处接地装置所检项目合格。			

27	GX-B1329/21-5-25116~25138	2025. 4. 3	<p>本次共检氧化锌避雷器23组，23组所检项目合格。</p> <p>。</p>	
28	GX-B1313/21-5-25033~25034	2025. 4. 7	<p>本次共检电力变压器2台，2台电力变压器所检项目合格。</p> <p>。</p>	

29	GX-B1323/21-5-25011~25015	2025. 4. 7	所检项目合格。	
30	GX-B1321/20-5-25070~25081	2025. 4. 7	本次共检电力电缆12条，12条电力电缆所检项目合格。	

31	GX-B1495/20-5-25071~25078	2025. 4. 7	本次共检高压开关柜8台，8台高压开关柜所检项目合格。 。	
32	GX-B1321/20-5-25061~25069	2025. 4. 7	本次共检电力电缆9条，9条电力电缆所检项目合格。	

33	GX-B1310/21-5-25052	2025/4/8	符合标准要求。		
34	GX-B1310/21-5-25053	2025/4/8	符合标准要求。		

35	GX-B1310/21-5-25054	2025/4/8	符合标准要求。	
36	GX-B1310/21-5-25055	2025/4/8	符合标准要求。	

37	GX-B1310/21-5-25056	2025/4/8	符合标准要求。	
38	GX-B1310/21-5-25057	2025/4/8	符合标准要求。	

39	GX-B1310/21-5-25058	2025/4/8	符合标准要求。	
40	GX-B1310/21-5-25059	2025/4/8	符合标准要求。	

41	GX-B1310/21-5-25060	2025/4/8	符合标准要求。	
42	GX-B1310/21-5-25061	2025/4/8	符合标准要求。	

43	GX-B1310/21-5-25062	2025/4/8	符合标准要求。			
44	GX-B1310/21-5-25063	2025/4/8	符合标准要求。			

45	GX-B1310/21-5-25064	2025/4/8	符合标准要求。			
46	GX-B1310/21-5-25065	2025/4/8	符合标准要求。			

47	GX-B1310/21-5-25066	2025/4/8	符合标准要求。	
48	GX-B1310/21-5-25067	2025/4/8	符合标准要求。	

49	GX-B1310/21-5-25068	2025/4/8	符合标准要求。	
----	---------------------	----------	---------	---