

序号	报告编号	发布日期	结论	影像资料
1	GX-B1372/22-F-250409~250413	2025.6.3	所检项目合格	
2	GX-B1601/22-F-250380~250388	2025.6.3	所检项目合格	
3	GX-B1540/20-F-251420-251442	2025.6.3	所检项目合格	


4	GX-B1540/20-F-251124~251148	2025.6.3	所检项目合格	
5	GX-B1540/20-F-251149~251173	2025.6.3	所检项目合格	
6	GX-B1540/20-F-251174~251198	2025.6.3	所检项目合格	

7	GX-B1540/20-F-251199~251223	2025.6.3	所检项目合格	
8	GX-B1568/22-F-25272	2025.6.3	所检项目合格	
9	GX-B1568/22-F-25267~25271	2025.6.3	所检项目合格	


10	GX-B1601/22-F-250438	2025.6.3	所检项目合格	
11	GX-B1593/21-F-25181~25182	2025.6.3	所检项目合格	
12	GX-B1603/22-F-250140~250143	2025.6.3	所检项目合格	


13	GX-B1602/22-F-25034~25035	2025.6.3	所检项目合格	 2025/5/31
14	GX-B1540/20-F-251149~251173	2025.6.3	所检项目合格	 2025.5.10
15	GX-B1540/20-F-251174~251198	2025.6.3	所检项目合格	 2025.5.11

16	GX-B1529/20-F-25115-25117	2025.6.4	本次共检验报警仪 3台, 3台所检项目合格。	
17	GX-B1529/20-F-25143-25147	2025.6.4	本次共检验报警仪 5台, 5台所检项目合格	
18	GX-B1528/20-F-25114-25118	2025.6.4	本次共检验报警仪 5台, 5台所检项目合格。	

19	GX-B1528/20-F-25096-25098	2025.6.4	本次共检验报警仪 3台，3台所检项目合格。	
20	GX-B1542/21-F-25184~25201	2025.6.4	本次共检验光干涉式 甲烷测定器18台，18台 所检项目合格。	
21	GX-B1542/21-F-25202~25211	2025.6.4	本次共检验光干涉式 甲烷测定器10台，10台 所检项目合格。	

22	GX-B1544/21-F-25022~25023	2025.6.4	本次共检验报警仪 2台，2台所检项目合格。	
23	GX-B1544/21-F-25024~25028	2025.6.4	本次共检验报警仪 5台，5台所检项目合格。	
24	GX-B1540/20-F-251226	2025.6.4	所检项目合格。	

25	GX-B1374/22-F-250534	2025.6.4	所检项目合格	 2025.6.1
26	GX-B1601/22-F-250476~250483	2025.6.5	所检项目合格	 2025.6.3
27	GX-B1540/20-F-251226	2025.6.5	所检项目合格。	 2025.5.20 2025.5.20 2025.5.11

28	GX-B1593/21-F-25187~25191	2025.6.5	所检项目合格	
----	---------------------------	----------	--------	---